




FIX-HANU-91



MATERIAL: NYLON (UL)
FLAME CLASS: 94V-0
COLOUR: BLACK
UNIT: mm

Shrinking is normal status



HOLE IN CHASSIS